Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

430 IN INTERSECTION NY Spills \$104880300 NNE BOYNTON AVE & AVE X N/A

1/2-1 BROOKLYN, NY

0.675 mi. 3562 ft.

 Relative:
 SPILLS:

 Higher
 Name:
 IN INTERSECTION

 Actual:
 Address:
 BOYNTON AVE & AVE X

 11 ft.
 City,State,Zip:
 BROOKLYN, NY

Spill Number/Closed Date: 0009163 / 2005-12-12

Facility ID: 0009163

 Facility Type:
 ER

 DER Facility ID:
 173781

 Site ID:
 209607

 DEC Region:
 2

Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 2000-11-08 Investigator: SXAHMED Referred To: Not reported Reported to Dept: 2000-11-08 CID: 390

Water Affected: Not reported
Spill Source: Commercial Vehicle

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2000-11-08
Spill Record Last Update: 2005-12-14
Spiller Name: Not reported
Spiller Company: ABLE BUS CO
Spiller Address: Not reported

Spiller Company: 001 Contact Name: UNK

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

ROMMEL 11/02/2005, SA: Called NRC, they have the same information on thier record under the case no: 547652. They adviced to contact 718 354 4121 for further information. Talked to the person, he told some

one will call me back and will provide required information.

12/09/2005: John Grathwol and I visited this spill site on 12/08/2005 at around 4:10pm. The correct address is Boynton Place and Avenue X. Inspected the road and surrounding area. There is a parking lot for school buses very near to that site. 5 school buses were parked on the street at that location. No sign or mark of anti-freeze on the road. Took pictures. Spill can be closed. (Sadique) 12/12/2005: The

spill is closed. (Sadique) "

Remarks: "bus leaked anti-freeze - unk further info - unk clean up "

All Materials:

 Site ID:
 209607

 Operable Unit ID:
 831475

 Operable Unit:
 01

 Material ID:
 543121

 Material Code:
 0043A

Map ID Direction Distance Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

Material Name: antifreeze
Case No.: Not reported
Material FA: Other
Quantity: .00
Units: G
Recovered: .00

Oxygenate: Not reported